

GOLI Electric Inc. Canada
Subject: Install GOLI CTL Burner
Time to Complete: 2 – 5 Minutes

Release Date: 03/05/2021 Revision Date: 05/05/2021 SOP Owner: Engineering

Compatibility

GOLI CTL Burner will not fit, if

The Oven Vent (typically located below the rear-left or rear-right burner) is 0.5" higher than the center hole of the drip pan.

Note: please contact GOLI Electric Inc. for a solution.

